

**COWLITZ COUNTY**

<b>SITE ID:</b>	<b>Fuel Processors Inc</b>	Cleanup Site ID: 76	FS ID: 810
Alternate Name(s):		Fuel Processors Inc, OIL RE REFINING CO INC	
<b>LOCATION:</b>	WRIA: 27	Lat/Long: 45.902 -122.754	<a href="#">View Vicinity Map</a>
Address: 701 BOZARTH WOODLAND 98674		Township Range Section 5N 1W 24	Legislative District: 20 Congressional District: 3
<b>STATUS:</b>	<b>Cleanup Started</b>	Rank: 3	<a href="#">View Site Web Page</a> <a href="#">View Site Documents</a>
Responsible Unit: Southwest		Site Manager: Leja, Stan	
Is Brownfield?		Statute: MTCA	
Has Environmental Covenant?		Is PSI Site?	
NFA Received?		NFA Date: NFA Reason:	

**ASSOCIATED CLEANUP UNIT(s)**

culD	Cleanup Unit Name	Unit Type	Process Type	Unit Status	Size (Acres)	ERTS ID
556	Fuel Processors Inc	Upland	Ecology-supervised or conducted	Cleanup Started		

**SITE ACTIVITIES:**

Applies to:	Related ID (Unit-LUST-VCP)	Activity Display Name	Status	Start Date	End Date	Legal Mechanism	Performed By	Project Manager
CleanupSite		Early Notice Letter(s)			12/13/1994			Petersen, Kaia
CleanupSite		Site Hazard Assessment/Federal Site Inspection	Completed	4/7/1997	4/7/1997		Ecology	Petersen, Kaia
CleanupSite		Hazardous Sites Listing/NPL			8/19/1997			Southwest Region
CleanupSite		Order/Decree/Amendment		9/17/2007				Leja, Stan
CleanupSite MilestoneTyp		Ecology Remedial Investigation and/or Feasibility Study	Planned	9/1/2006	9/1/2008	Agreed Order	PLP	Leja, Stan
CleanupSite MilestoneTyp		Ecology Remedial Investigation and/or Feasibility Study	Completed	12/1/1999	12/30/2001		Ecology	Southwest Region

**AFFECTED MEDIA & CONTAMINANTS:**
**Media:**

Contaminant:	Ground Water	Surface Water	Soil	Sediment	Air	Bedrock
Halogenated Organics	S		C			
Metals Priority Pollutants	S		C			
Petroleum Products-Unspecified	S		C			

**Key:**

B - Below Cleanup Level  
C - Confirmed Above Cleanup Level  
S - Suspected

R - Remediated  
RA - Remediated-Above  
RB - Remediated-Below

CleanupSiteDetails2014